

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- ✓ Acceptable
- ⚠ Questionable
- ✗ Unacceptable
- 🔄 Resample
- ⚪ No Classification
- Not Tested
- ✓ "Dot" - Most Recent Order
- 📅 "Color" - Result within 12 months
- ⚪ "Grey" - Result older than 12 months










Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
Requires Service Work														
FRANKLIN SUB #2 TRANSFORMER	20586-2 1	TRANSFORMER 274,100 lbs	OIL 12,250	37500 3/60	12Jun2018	✓	⚪	✓	✓	✓	✓	—	NON-PCB 12Jun2018	REPAIR - PAINT
FRANKLIN SUB #4 TRANSFORMER	C-05397-5-1 2	TRANSFORMER 179,100 lbs	OIL 5,933	37500 3/60	12Jun2018	✓	⚪	⚠	✓	✓	✓	—	NON-PCB 12Jun2018	REPAIR - PAINT
FRANKLIN SUB #3 TRANSFORMER	C-03814-5-1 3	TRANSFORMER 155,200 lbs	OIL 5,945	25000 3/60	12Jun2018	✓	⚪	✓	✓	✓	✓	—	NON-PCB 12Jun2018	REPAIR - PAINT
FRANKLIN SUB #1 TRANSFORMER	20586-1 4	TRANSFORMER 274,100 lbs	OIL 12,250	37500 3/60	12Jun2018	⚠	✗	✓	✓	✓	✓	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE CHECK P/V GAUGE, N2 SYS; ADJ. PRESSURE REPAIR - PAINT
FRANKLIN SUB SYNCHRONOS COND	2981095 5	TRANSFORMER 92,500 lbs	OIL 3,400	15000 3/60	12Jun2018	✓	🔄	✓	✓	✓	✓	—	NON-PCB 12Jun2018	REPAIR - PAINT
FRANKLIN SUB	7024255 6	POTENTIAL TRANSFORMER	OIL 9	500 1/60	12Jun2018	—	—	—	—	—	—	—	PCB CONTAMINATED	PCB REDUCTION REPAIR - PAINT
FRANKLIN SUB	7024294 7	POTENTIAL TRANSFORMER	OIL 9	500 1/60	12Jun2018	—	—	—	—	—	—	—	PCB CONTAMINATED	PCB REDUCTION REPAIR - PAINT
FRANKLIN SUB	7024254 8	POTENTIAL TRANSFORMER	OIL 9	500 1/60	12Jun2018	—	—	—	—	—	—	—	PCB CONTAMINATED	PCB REDUCTION REPAIR - PAINT



















Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

-  Acceptable
-  Questionable
-  Unacceptable
-  Resample
-  No Classification
-  Not Tested
-  "Dot" - Most Recent Order
-  "Color" - Result within 12 months
-  "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
SCRAP	0141A3654-2039	OCB	OIL 265	3/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
#1 SUB 2300 BUS XFMR	PGP-1162110	TRANSFORMER 48,100 lbs	OIL 1,695	10000 3/60	13Jun2018							-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
#1 SUB	L24620411	TRANSFORMER 26,470 lbs	OIL 1,220	10000 3/60	13Jun2018							-	NON-PCB 13Jun2018	REPAIR - PAINT
#1 SUB	351944712	TRANSFORMER 5,230 lbs	OIL 2,030	10000 3/60	13Jun2018							-	NON-PCB 13Jun2018	REPAIR - PAINT
FRANKLIN SUB	NO NAMEPLATE 13	TRANSFORMER	OIL 25		12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	NO NAMEPLATE 14	TRANSFORMER	OIL 25		12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	UNABLE TO READ 15	POTENTIAL TRANSFORMER	OIL 15		12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	UNABLE TO READ 16	POTENTIAL TRANSFORMER	OIL 15		12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

 Acceptable


 Questionable


 Unacceptable


 Resample









 No Classification

 Not Tested

 "Dot" - Most Recent Order

 "Color" - Result within 12 months

 "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
FRANKLIN SUB	UNABLE TO READ 17	POTENTIAL TRANSFORMER	OIL 15		12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	UNABLE TO READ 18	POTENTIAL TRANSFORMER	OIL 15		12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	UNABLE TO READ 19	TRANSFORMER	OIL 20	1/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	ILLEGIBLE 20	TRANSFORMER	OIL 20	1/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	ILLEGIBLE 21	TRANSFORMER	OIL 20	1/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
SCRAP	3486418 22	POTENTIAL TRANSFORMER 1,070 lbs	OIL 43	1/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
FRANKLIN SUB STATION POWER	6189985 23	TRANSFORMER 900 lbs	OIL 150	150 3/60	12Jun2018							-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB RIVER PUMP XFMR	36548 24	TRANSFORMER	OIL 420	500 1/60	12Jun2018		-		-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- ✓ Acceptable
- ⚠ Questionable
- ✖ Unacceptable
- 🔄 Resample
- ⚪ No Classification
- Not Tested
- 🟢 "Dot" - Most Recent Order
- 🟡 "Color" - Result within 12 months
- ⚪ "Grey" - Result older than 12 months










Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
FRANKLIN SUB RIVER PUMP XFMR	3654726	TRANSFORMER	OIL 420	500 1/60	12Jun2018	⚪	—	⚪	—	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB SPARE	702429627	POTENTIAL TRANSFORMER	OIL 9	500 1/60	12Jun2018	—	—	—	—	—	—	—	PCB CONTAMINATED	PCB REDUCTION REPAIR - PAINT
FRANKLIN SUB SPARE	640884728	POTENTIAL TRANSFORMER	OIL 9	500	12Jun2018	—	—	—	—	—	—	—	PCB CONTAMINATED	PCB REDUCTION REPAIR - PAINT
BAGHOUSE	H88823729	TRANSFORMER 48,800 lbs	OIL 1,830	10000 3/60	14Jun2018	🟢	🟢	🟢	🟢	⚠	🟢	—	NON-PCB 14Jun2018	REPAIR - PAINT
SCRAP	365471731	TRANSFORMER 12,275 lbs	OIL 558	1000 3/60	12Jun2018	—	—	—	—	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
BACK OF PLANT PLATFORM ABOVE L3	312813232	TRANSFORMER	OIL 50	50 1/60	13Jun2018	—	—	—	—	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
BACK OF PLANT PLATFORM ABOVE L3	632003833	TRANSFORMER	OIL 74	125 1/60	13Jun2018	—	—	—	—	—	—	—	PCB 13Jun2018	PCB REDUCTION REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
POLE 5	N994911-YKY34	POP TOP XFMR 349 lbs	OIL 25	25 1/60	13Jun2018	—	—	—	—	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT





























Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

-  Acceptable
-  Questionable
-  Unacceptable
-  Resample
-  No Classification
-  Not Tested
-  "Dot" - Most Recent Order
-  "Color" - Result within 12 months
-  "Grey" - Result older than 12 months










Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
SPARE OUT OF SERVICE	SDV 5787-01 35	TRANSFORMER 23,100 lbs	OIL 681	5000 3/60	13Jun2018								NON-PCB 13Jun2018	REPAIR - PAINT
#9 SUB/21" MILL	L247486 36	TRANSFORMER 36,470 lbs	OIL 1,220	10000 3/60	14Jun2018								NON-PCB 14Jun2018	REPAIR - PAINT
POLE 5	113694 37	POP TOP XFRMR	OIL 15	10 1/60	13Jun2018								NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
POLE 5	42426 38	POP TOP XFRMR	OIL 10	25 1/60	13Jun2018								NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
POLE 11	UNABLE TO READ 39	POP TOP XFRMR	OIL 25	1/60	13Jun2018								NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
POLE 4	D4491-1 40	POP TOP XFRMR	OIL 10	50 1/60	13Jun2018								NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
POLE 3	87V7548 42	TRANSFORMER	R-TEMP 350	500 3/60	13Jun2018								NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
MILL POWER	57233 46	SWITCH RECLOSER	OIL		13Jun2018								NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

-  Acceptable
-  Questionable
-  Unacceptable
-  Resample
-  No Classification
-  Not Tested
-  "Dot" - Most Recent Order
-  "Color" - Result within 12 months
-  "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
MILL POWER	53456 47	SWITCH RECLOSER	OIL		13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
MILL POWER	5548 48	SWITCH RECLOSER	OIL		13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
MILL POWER POLE	UNABLE TO READ 49	POP TOP XFRMR	OIL 10	50 1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
PLATFORM NEAR #1 SUB BETWEEN BUILDINGS	3128142 52	TRANSFORMER	OIL 25	50 1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
SPARE	83JL060053 53	CABINET XFRMR 5,156 lbs	OIL 305	300 3/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
SPARE LTC FOR TC 411	50055 54	ARC IN OIL LTC	OIL		13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
PLATFORM NEAR MAIN GATE	3137624 56	REGULATING TRANSFORMER	OIL 74	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
PLATFORM NEAR MAIN GATE	98A322567 57	POP TOP XFRMR 585 lbs	OIL 31	50 1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT


Location


Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

 Acceptable

 Questionable


 Unacceptable


 Resample





 No Classification

 Not Tested

 "Dot" - Most Recent Order

 "Color" - Result within 12 months

 "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
PLATFORM NEAR MAIN GATE	95A394072 58	POP TOP XFRMR 681 lbs	OIL 43	50 1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
ACROSS FROM OPERATIONS DOOR	S35010 59	TRANSFORMER 1,410 lbs	OIL 40	75 1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
ACROSS FROM OPERATIONS DOOR	79A195018 60	POP TOP XFRMR 887 lbs	OIL 50	75 1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
ACROSS FROM OPERATIONS DOOR	NO NAMEPLATE 61	TRANSFORMER	OIL 500	3/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
#1 SUB	H880983 62	TRANSFORMER	OIL 1,060	10000 3/60	13Jun2018					-	-	-	NON-PCB 13Jun2018	REPAIR - PAINT
DOWN ALLEY FROM #1 SUB	4145475 66	TRANSFORMER	OIL 50	75 1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
DOWN ALLEY FROM #1 SUB	6320037 67	TRANSFORMER	OIL 74	125 1/60	13Jun2018	-	-	-	-	-	-	-	PCB 13Jun2018	PCB REDUCTION REPAIR - PAINT
NEAR STEEL SALES BLDG	35572 68	SWITCH RECLOSER	OIL		14Jun2018	-	-	-	-	-	-	-	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- ✓ Acceptable
- ⚠ Questionable
- ✗ Unacceptable
- 🔄 Resample
- ⚪ No Classification
- Not Tested
- "Dot" - Most Recent Order
- 📅 "Color" - Result within 12 months
- 🕒 "Grey" - Result older than 12 months










Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
PLATFORM NEAR K7 DOOR	3145112 69	TRANSFORMER	OIL 55	50 1/60	14Jun2018	—	—	—	—	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
PLATFORM NEAR K7 DOOR	3145106 70	TRANSFORMER	OIL 55	50 1/60	14Jun2018	—	—	—	—	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
PLATFORM NEAR K7 DOOR	3145102 71	TRANSFORMER	OIL 55	50	14Jun2018	—	—	—	—	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
PLATFORM ACROSS FROM RR TRACKS K BLDG	98A322566 75	TRANSFORMER 585 lbs	OIL 31	50 1/60	14Jun2018	—	—	—	—	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
2ND PLATFORM FROM MAIN GATE	ILLEGIBLE 76	TRANSFORMER	OIL	1/60	14Jun2018	—	—	—	—	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
2ND PLATFORM FROM MAIN GATE	2652269 77	TRANSFORMER 1,290 lbs	OIL 42	75 1/60	14Jun2018	—	—	—	—	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
DOWN ALLEY FROM #1 SUB RIGHT	3344029 80	POP TOP XFRMR	OIL 2	1 1/60	14Jun2018	—	—	—	—	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
DOWN ALLEY FROM #1 SUB LEFT	6024327 81	POP TOP XFRMR	OIL 4	1 1/60	14Jun2018	—	—	—	—	—	—	—	PCB CONTAMINATED	PCB REDUCTION REPAIR - PAINT

























Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

-  Acceptable
  Questionable
  Unacceptable
  Resample
  No Classification
  Not Tested
 "Dot" - Most Recent Order
 "Color" - Result within 12 months
 "Grey" - Result older than 12 months










Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
BLDG H	3160927 82	TRANSFORMER 2,835 lbs	OIL	200 1/60	14Jun2018	-	-	-	-	-	-	-	PCB CONTAMINATED	PCB REDUCTION REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
BLDG H	3160928 83	TRANSFORMER 2,835 lbs	OIL 55	200 1/60	14Jun2018	-	-	-	-	-	-	-	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
MAIN GATE 42	C-09189-1-1 102	TRANSFORMER 1,750 lbs	OIL 60	112 3/60	13Jun2018							-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
RESTAURANT 43	L247970 103	TRANSFORMER 3,665 lbs	OIL 134	500 3/60	14Jun2018							-	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
RESTAURANT 44	125215 104	TRANSFORMER 5,500 lbs	OIL 178	225 3/60	14Jun2018							-	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
RESTAURANT	1381293 105	TRANSFORMER 1,775 lbs	OIL 195	225 3/60	14Jun2018							-	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
#1 SUB EAST A	338852 332	OCB 6,185 lbs	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
#1 SUB EAST B	338852 333	OCB 6,185 lbs	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT





Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

-  Acceptable
-  Questionable
-  Unacceptable
-  Resample
-  No Classification
-  Not Tested
-  "Dot" - Most Recent Order
-  "Color" - Result within 12 months
-  "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
#1 SUB EAST C	338852 334	OCB 6,185 lbs	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
#1 SUB WEST A	338851 335	OCB 6,185 lbs	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
#1 SUB WEST B	338851 336	OCB 6,185 lbs	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
#1 SUB WEST C	338851 337	OCB 6,185 lbs	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB #5 FURNACE	27203 338	OCB 4,928 lbs	OIL 220	3/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB #7 FURANCE	0141A3654-201 341	OCB 6,146 lbs	OIL 265	3/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB #8 FURNACE	22422 342	OCB 4,928 lbs	OIL 220	3/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB #9 FURNACE	19975 343	OCB 5,188 lbs	OIL 205	3/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- ✓ Acceptable
- ⚠ Questionable
- ✗ Unacceptable
- 🔄 Resample
- ⬇ No Classification
- Not Tested
- "Dot" - Most Recent Order
- 🚧 "Color" - Result within 12 months
- 🕒 "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
FRANKLIN SUB EAST BANK 1A-2A	18168 345	OCB 5,188 lbs	OIL 205	3/60	12Jun2018	✗	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB WEST BANK 1B-2B	18167 346	OCB 5,188 lbs	OIL 205	3/60	12Jun2018	✗	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB #2 TRANS	22424 347	OCB 4,928 lbs	OIL 220	3/60	12Jun2018	✗	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB BUSS TIE	18166 348	OCB 5,188 lbs	OIL 205	3/60	12Jun2018	✓	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB #4 TRANS	22421 349	OCB 4,928 lbs	OIL 220	3/60	12Jun2018	✗	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB MILL POWER	18178 350	OCB 5,188 lbs	OIL 205	3/60	12Jun2018	✗	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB #1 TRANS	22423 351	OCB 4,928 lbs	OIL 220	3/60	12Jun2018	✗	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB RIVER PUMP	K-636830-210 352	OCB 900 lbs	OIL 25	3/60	12Jun2018	✓	✓	✓	⬇	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- Acceptable
 Questionable
 Unacceptable
 Resample
 No Classification
 Not Tested
- "Dot" - Most Recent Order
 "Color" - Result within 12 months
 "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
FRANKLIN SUB	5696202362	CURRENT TRANSFORMER 4,325 lbs	OIL 250	250 1/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	5696203363	POTENTIAL TRANSFORMER 13,450 lbs	OIL 940	1/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	5696204364	POTENTIAL TRANSFORMER 13,450 lbs	OIL 940	1/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	5696201365	CURRENT TRANSFORMER 4,325 lbs	OIL 250	1/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB 138 MN.BREAKER	308420366	OCB 25,475 lbs	OIL 1,140	1/60	12Jun2018					-	-	-	PCB CONTAMINATED	PCB REDUCTION MONITOR PAINT CONDITION
FRANKLIN SUB 138 MN.BREAKER	308420368	OCB 25,475 lbs	OIL 1,140	1/60	12Jun2018					-	-	-	PCB CONTAMINATED	PCB REDUCTION MONITOR PAINT CONDITION
CONDITIONING	90046376	TRANSFORMER 10,450 lbs	OIL 312	2000 3/60	13Jun2018							-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB RIVER PUMP	PXH-0626404	TRANSFORMER 14,650 lbs	OIL 512	2500 3/60	12Jun2018							-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- Acceptable
 Questionable
 Unacceptable
 Resample
 No Classification
 Not Tested
- "Dot" - Most Recent Order
 "Color" - Result within 12 months
 "Grey" - Result older than 12 months










Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
SPARE	50055 411	TRANSFORMER 43,100 lbs	OIL 1,805	3750 3/60	13Jun2018								NON-PCB 13Jun2018	REPAIR - PAINT
SPARE FOR NEW EAF	16210898 418	FURNACE TRANSFORMER 364,700 lbs	OIL 9,005	84000 3/60	13Jun2018								NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR GAUGE MONITOR PAINT CONDITION
FRANKLIN SUB TRF 2	29100 421	OCB 5,158 lbs	OIL 220	38 3/60	12Jun2018								NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB TRF 1	29099 422	OCB 5,158 lbs	OIL 220	3/60	12Jun2018								NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	29096 423	OCB 5,158 lbs	OIL 220	3/60	12Jun2018								NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	29098 424	OCB 5,158 lbs	OIL 220	3/60	12Jun2018								NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB	29097 425	OCB 5,158 lbs	OIL 220	3/60	12Jun2018								NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB 1+8 SS EAST FEEDER	29095 426	OCB 5,158 lbs	OIL 220	3/60	12Jun2018								NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT















Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

-  Acceptable
-  Questionable
-  Unacceptable
-  Resample
-  No Classification
-  Not Tested
-  "Dot" - Most Recent Order
-  "Color" - Result within 12 months
-  "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
FRANKLIN SUB 23 OCB	29094 427	OCB 5,158 lbs	OIL 220	3/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
FRANKLIN SUB 24 OCB	27072 428	OCB 7,731 lbs	OIL 410	38 3/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
WASTE WATER	PXF-0521 429	TRANSFORMER 7,900 lbs	OIL 289	1000 3/60	12Jun2018					-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
US FILTERS	98K2700 440	CABINET XFRMR 14,000 lbs	OIL 530	2000 3/60	13Jun2018					-	-	-	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT
MILL POWER	98J2697 445	TRANSFORMER 40,610 lbs	OIL 1,550	7500 3/60	13Jun2018					-	-	-	NON-PCB 13Jun2018	REPAIR - PAINT
FRANKLIN SUB/EAST #1 OIL STOR. TANK	NONE 7007	STORAGE TANK	OIL 1,500		12Jun2018		-	-	-	-	-	-	NON-PCB 12Jun2018	REPAIR - PAINT
FRANKLIN SUB OLD MAIN XMFR	NO NAMEPLATE 7369	TRANSFORMER	OIL 5,000		12Jun2018		-	-	-	-	-	-	NON-PCB 27Jul1990	PCB TEST REPAIR GAUGE REPAIR - PAINT
SCRAP YARD	NO NAMEPLATE 9059	OCB	OIL 100	1/60	12Jun2018	-	-	-	-	-	-	-	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- ✓ Acceptable
- ⚠ Questionable
- ✖ Unacceptable
- 🔄 Resample
- ⚪ No Classification
- Not Tested
- 🟢 "Dot" - Most Recent Order
- 🟡 "Color" - Result within 12 months
- ⚪ "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
SCRAP YARD	NO NAMEPLATE 9060	OCB	OIL 100	1/60	12Jun2018	—	—	—	—	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
SCRAP YARD	NO NAMEPLATE 9061	OCB	OIL 100	1/60	12Jun2018	—	—	—	—	—	—	—	NON-PCB 12Jun2018	PCB TEST ACCEPTABLE REPAIR - PAINT LOW LIQUID - VERIFY AND RESTORE
Normal Monitoring														
POLE 3	292488 41	TRANSFORMER 10,390 lbs	OIL 390	1000 3/60	13Jun2018	—	—	—	—	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION
MILL POWER	53457 43	SWITCH RECLOSER	OIL		13Jun2018	—	—	—	—	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION
MILL POWER	53455 44	SWITCH RECLOSER	OIL		13Jun2018	—	—	—	—	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION
MILL POWER	53454 45	SWITCH RECLOSER	OIL		13Jun2018	—	—	—	—	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION
FRANKLIN SUB 138 MN.BREAKER	308420 367	OCB 25,475 lbs	OIL 1,140	1/60	12Jun2018	🟢	⚪	🟢	⚪	—	—	—	NON-PCB 12Jun2018	MONITOR PAINT CONDITION
NEW LRF MAIN TANK	7002814 413	FURNACE TRANSFORMER 112,000 lbs	OIL 2,830	35000 3/60	13Jun2018	⚪	⚪	⚠	🟢	✖	🟢	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- ✓ Acceptable
- ⚠ Questionable
- ✗ Unacceptable
- 🔄 Resample
- ⚪ No Classification
- Not Tested
- "Dot" - Most Recent Order
- 🚨 "Color" - Result within 12 months
- ⚪ "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
NEW EAF REACTOR TANK	16240898 419	SELECTOR COMPARTMENT	OIL		13Jun2018	✓	✓	✓	✓	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION
NEW LRF	7002814 420	DEENERGIZED TAP CHANGER	OIL		13Jun2018	✓	✓	✓	✓	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR LEVEL & TEMP; CHECK GAUGE MONITOR PAINT CONDITION
SHIPPING	110503-8 442	TRANSFORMER 9,600 lbs	OIL 546	500 3/60	14Jun2018	✓	✓	✓	✓	—	—	—	NON-PCB 14Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION
MILL POWER	ST119857637 452	TRANSFORMER 29,330 lbs	OIL 1,310	5000 3/60	13Jun2018	✓	⚠	⚠	✓	—	—	—	NON-PCB 13Jun2018	RETEST ONE YEAR MONITOR PAINT CONDITION
NEW EAF MAIN TANK	16240898 455	TRANSFORMER 364,700 lbs	OIL 9,005	84000 3/60	13Jun2018	✓	✓	✓	✓	✓	✓	✓	NON-PCB 13Jun2018	RETEST ONE YEAR MONITOR PAINT CONDITION
NEW EAF LTC TANK	16240898 456	LOAD TAP CHANGER	OIL 750		13Jun2018	✓	✓	✓	⚪	✓	✓	✓	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE MONITOR PAINT CONDITION
WAREHOUSE	126706 457	CABINET XFMR 5,400 lbs	OIL 243	500 3/60	13Jun2018	✓	✓	⚠	✓	—	—	—	NON-PCB 13Jun2018	PCB TEST ACCEPTABLE
No Recommendation / Not Tested														
FRANKLIN SUB RIVER PUMP XFMR	36549 25	TRANSFORMER	OIL 420	500 1/60	13Jun2018	⚪	—	⚪	—	—	—	—	15Sep1980	UNABLE TO OBTAIN SAMPLE

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- ✓ Acceptable
- ⚠ Questionable
- ✖ Unacceptable
- 🔄 Resample
- ⚪ No Classification
- ⚪ Not Tested
- 🟢 "Dot" - Most Recent Order
- 🟡 "Color" - Result within 12 months
- ⚪ "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
SCRAP	3951686 30	TRANSFORMER	OIL 53	75 1/60	13Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN / LIQ. LEV. LOW
SOUTH PLANT PLATFORM	UNABLE TO READ 50	TRANSFORMER	OIL	1/60	13Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN SAMPLE
SOUTH PLANT PLATFORM	UNABLE TO READ 51	TRANSFORMER	OIL		14Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN SAMPLE
POLE BY E6 DOOR	UNABLE TO READ 55	POP TOP XFRMR	OIL 20	1/60	13Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN / LIQ. LEV. LOW
BACK OF PLANT PLATFORM ABOVE K8 DOOR	UNABLE TO READ 63	POP TOP XFRMR	OIL		13Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN SAMPLE
BACK OF PLANT PLATFORM ABOVE K8 DOOR	UNABLE TO READ 64	POP TOP XFRMR	OIL		13Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN SAMPLE
BACK OF PLANT PLATFORM ABOVE K8 DOOR	UNABLE TO READ 65	POP TOP XFRMR	OIL		13Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN SAMPLE
PLATFORM NEAR K6 DOOR	UNABLE TO READ 72	TRANSFORMER	OIL 50	1/60	14Jun2018	⚪	⚪	⚪	⚪	⚪	⚪	⚪		UNABLE TO OBTAIN SAMPLE

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

- Acceptable
 Questionable
 Unacceptable
 Resample
 No Classification
 Not Tested
- "Dot" - Most Recent Order
 "Color" - Result within 12 months
 "Grey" - Result older than 12 months










Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
PLATFORM NEAR K6 DOOR	UNABLE TO READ 73	TRANSFORMER	OIL	1/60	14Jun2018	-	-	-	-	-	-	-		UNABLE TO OBTAIN SAMPLE
PLATFORM NEAR K6 DOOR	UNABLE TO READ 74	TRANSFORMER	OIL 50	1/60	14Jun2018	-	-	-	-	-	-	-		UNABLE TO OBTAIN SAMPLE
PLATFORM WEST OF #1 SUB	78	TRANSFORMER	OIL	1/60	14Jun2018	-	-	-	-	-	-	-		UNABLE TO OBTAIN SAMPLE
PLATFORM WEST OF #1 SUB	79	TRANSFORMER	OIL	1/60	14Jun2018	-	-	-	-	-	-	-		UNABLE TO OBTAIN SAMPLE
BLDG H	3160929 84	TRANSFORMER 2,835 lbs	OIL 55	200 1/60	14Jun2018	-	-	-	-	-	-	-		UNABLE TO OBTAIN / LIQ. LEV. LOW
FRANKLIN SUB #6 FURNACE	18179 344	OCB 5,188 lbs	OIL 205	3/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 27Jul1990	UNABLE TO OBTAIN SAMPLE
FRANKLIN SUB/WEST #2 OIL STOR. TANK	NONE 7006	STORAGE TANK	OIL 1,500		13Jun2018		-	-	-	-	-	-	NON-PCB 18Nov1992	UNABLE TO OBTAIN SAMPLE
FRANKLIN SUB OLD MAIN XFMR	NO NAMEPLATE 7370	TRANSFORMER	OIL 5,000	3/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 27Jul1990	UNABLE TO OBTAIN SAMPLE

Location

Customer: 1009000-Warren Steel Holdings

City / State: Warren, OH

Legend

-  Acceptable
-  Questionable
-  Unacceptable
-  Resample
-  No Classification
-  Not Tested
-  "Dot" - Most Recent Order
-  "Color" - Result within 12 months
-  "Grey" - Result older than 12 months

Sub Name / Unit No.	Serial No. / TC No.	Equip Type / Weight	Fluid Type / Gallons	kVA / Phase & Cycle	Last Sample Date	LS	KF	DGA	LPF	INH	ICP	FUR	PCB Class / PCB Date	Most Recent Service-Recommendations
SCRAP YARD	15838-2 9062	OCB	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 05Jan2012	UNABLE TO OBTAIN / LIQ. LEV. LOW
SCRAP YARD	15838-2 9063	OCB	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 05Jan2012	UNABLE TO OBTAIN / LIQ. LEV. LOW
SCRAP YARD	15838-2 9064	OCB	OIL 97	1/60	13Jun2018	-	-	-	-	-	-	-	NON-PCB 05Jan2012	UNABLE TO OBTAIN / LIQ. LEV. LOW